



Close-up: Illegal fitting on 28" Bomu-Bonny Trans Niger Pipeline at Otokolomabie/Oloma.  
Picture was taken during Joint Investigation of 9<sup>th</sup> May 2015.