



Close-up: Illegal fitting on 20" Opukushi – Brass Creek Pipeline at Tamogbene. Picture was taken during Joint Investigation of 15th May 2015.