



Overview: Location of spill point on 28" Nkpoku-Bomu Pipeline Right of Way at Kpoghor. Picture was taken during Joint Investigation of 29th May 2015.



Close-up: Hacksaw cut on 28" Nkpoku-Bomu Pipeline at Kpoghor. Picture was taken during Joint Investigation of 29th May 2015.