



Overview: Part of spill impact on 28" Nkpoku - Bomu Pipeline Right of Way at B-Dere. Picture was taken during Joint Investigation of 29<sup>th</sup> May 2015.



Close-up: Illegal fitting on 28" Nkpoku - Bomu Pipeline at B-Dere. Picture was taken during Joint Investigation of 29<sup>th</sup> May 2015.