




Overview: Part of spill impact on 12" Imo River – Ogale Pipeline Right of Way at Komkom. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2015.



Close-up: Illegal fittings on 12" Imo River – Ogale Pipeline at Komkom. Picture was taken during Joint Investigation of 20<sup>th</sup> May 2015.