



Overview: Part of Spill Impact around Ibaa manifold 8" Header at Ibaa. Picture was taken during Joint Investigation of 6th May 2016.



Close-up: Leak point on Ibaa manifold 8" Header at Ibaa. Picture was taken during Joint Investigation of 6th May 2016.