




Overview: Part of Spill Impact on 16" Egbema-Assa Pipeline Right of Way at Ekpeagah. Picture was taken during Joint Investigation of 5th June 2016.



Close-up: Illegal fitting on 16" Egbema-Assa Pipeline at Ekpeagah. Picture was taken during Joint Investigation of 5th June 2016.