



Overview: Part of spill impact on 8" Agbada2-Nkpoku Pipeline at Rukpokwu. Picture was taken during Joint Investigation of 9<sup>th</sup> August 2016.



Close-up: Non leaking Illegal point & leaking Illegal fitting on 8" Agbada2-Nkpoku Pipeline at Rukpokwu. Picture was taken during Joint Investigation of 9<sup>th</sup> August 2016.