




Overview: Part of spill impact on 18" Assa-Rumuekpe Pipeline Right of Way at Ochia. Picture was taken during Joint Investigation of 1st June 2017.



Close-up: 3" non leaking and leaking illegal fitting on 18" Assa-Rumuekpe Pipeline at Ochia. Picture was taken during Joint Investigation of 1st June 2017.