


Overview: Part of spill impact on 12"Imo River-Ogale Pipeline Right of Way at Okohia-Asa. Picture was taken during Joint Investigation of 2<sup>nd</sup> June 2017.



Close-up: Illegal fittings on 12"Imo River-Ogale Pipeline at Okohia-Asa. Picture was taken during Joint Investigation of 2<sup>nd</sup> June 2017.