



Close-up: Spill due to hacksaw cut on 6" ObigoNorth-Ogale pipeline at Ogale. Picture was taken during Joint Investigation of 23rd November, 2011.