



Overview: Part of spill impact on 24" Npoku-Bomu pipeline right of way at Biara. Picture was taken during Joint Investigation of 3rd November, 2011.



Close-up: Illegal fittings on 24" Npoku-Bomu pipeline at Biara. Picture was taken during Joint Investigation of 3rd November, 2011.