



Overview: Part of spill impact on 12" Cawthorne Channel pipeline right of way at Ilomaturu. Picture was taken during Joint Investigation of 23rd November, 2011.



Close-up: Spill due to failed weld on 12" Cawthorne Channel pipeline riser at Ilomaturu. Picture was taken during Joint Investigation of 23rd November, 2011.