

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1067829 JIV report S/N: 0340

*(Note: As practicable as possible the JIT report is to be signed in the field by all the participating parties)*

**A. GENERAL INFORMATION:**

1. Spill incident Number: 1067829 2. Type of incident\* OIL SPILL AND FIRE  
 3. Name of Location 201 BOMU - BONNY PIPELINE  
 4. Name of nearest community KPOR/K-DELE 5. State: RIVERS 6. LGA BOCKANA  
 7. Type of Production facility/Installation OIL PIPELINE 8. Asset owner/District PIPELINE

**B. INCIDENT INFORMATION:**

9. Details of incident

- a. Date of incident: 6<sup>TH</sup> NOVEMBER 2013  
 b. Start date/time of investigation: 2<sup>TH</sup> NOVEMBER 2013 : 13:30 Hours  
 c. Investigation End date: 10<sup>TH</sup> NOVEMBER 2013 investigation duration, days: Three (3) DAY  
 d. Description of spill point environment

- |   |   |   |
|---|---|---|
| <input type="checkbox"/> Firmed soil              | <input checked="" type="checkbox"/> Loose soil      | <input checked="" type="checkbox"/> Recently excavated area |
| <input type="checkbox"/> Under water              | <input checked="" type="checkbox"/> Swampy SEASONAL | <input type="checkbox"/> Exposed pipe surface               |
| <input type="checkbox"/> Well Platform (on Water) |   | <input type="checkbox"/> Drill Rig                          |
- e. Description of leak point (tick as applicable);
- |   |   |   |
|---|---|---|
| <input type="checkbox"/> Drilled hole                               | <input checked="" type="checkbox"/> Hack saw cut        | <input type="checkbox"/> Tear (_____).                      |
| <input type="checkbox"/> Complete Rupture                           | <input type="checkbox"/> Inward dent,                   | <input type="checkbox"/> Well head tampering                |
| <input type="checkbox"/> Failed Weld-on illegal hot tap valve,      | <input type="checkbox"/> Failed Clamp                   | <input type="checkbox"/> Missing Pipeline/Flowline          |
| <input type="checkbox"/> Crude oil theft (illegal bunkering) point, |   | <input type="checkbox"/> Third party tampering with Clamp   |
| <input type="checkbox"/> Third party tampering with valve setting,  |   | <input type="checkbox"/> Third party tampering with flange, |
| <input type="checkbox"/> Corrosion                                  | <input type="checkbox"/> Saver-pit over flow,           | <input type="checkbox"/> Surge vessel overflow,             |
| <input type="checkbox"/> Bulging Outward                            | <input type="checkbox"/> Flare System/Bund wall failure | <input type="checkbox"/> Accidental 3 <sup>rd</sup> party   |
| equipment impact  | <input type="checkbox"/> Valve Failure                  | <input type="checkbox"/> com unit failure                   |
| <input type="checkbox"/> Cold vent                                  |   |   |
- Relief valve failure       Others (specify) \_\_\_\_\_

f. Incident caused by:

- Third party interference (Sabotage , crude theft ; Line theft ; Accidental 3<sup>rd</sup> party damage )  
 Operational       Others (including Mystery spills) \_\_\_\_\_

g. Spill point coordinates

Measuring unit <u>METERS</u> <u>M/WNA (MID-BELT)</u>	
Northing:	Easting:
<u>72527.92</u>	<u>534933.09</u>

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 106 9829 JIV report S/N: 0340

**C. RISK ASSESSMENT**

10. Type of environment:

- Land       Swamp       Water       Seasonal swamp       Shoreline/Waterfront

i. Type of environment to which oil has spread:

- Land       Swamp **SEASONAL**       Water       River (identify) \_\_\_\_\_

ii. Weather condition

- Rain       Sunny       Dry       Wet       Windy       Hot       Cool

11. Distance from the nearest sensitive habitat

- Government reserved and designated protected area [      ,m]
- Drinking water source **NONE SEEN** [      ,m]
- Built up area **WITHIN AREA OF** [      ,m]
- Farmlands **IMPACT** [      ,m]
- Fish Farm/Pond [      ,m]
- Fishing net [      ,m]
- Others (specify).

12. Containment measures put in place;

- Booms       Trench       Dyke       Natural depression       Pit  
 Others: \_\_\_\_\_

13. Any pictures or video coverage?

[Y]      [N]

14. Was there any disruption to the investigation?

[Y]       [N]

If yes give brief description:

NOT APPLICABLE

**D. TYPE/NUMBERS OF PROPERTIES, IF ANY, FOUND WITHIN THE AREA OF SPREAD OF OIL**

15. Structures / Properties

S/N	Type of Structures	Description	Size	Number	Comments
		<b>NONE</b>			<b>WITHIN AREA OF IMPACT</b>

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1067829 JIV report S/N: 0340

S/N	Type of crops	Young	Medium	Matured	Quantity	Comments
	<u>RAFIA PALM</u>		✓	✓		<u>BURNT AND IMPACTED</u>

17. Fish/Nets/Ponds


S/N	Fish/Nets/Ponds	Description	Quantity/Size	Comments
	<u>NONE</u>	<u>WITHIN AREA OF IMPACT</u>		

18. Others (Specify) i.e. Animal Traps

S/N	Others	Description	Quantity/Size	Comments
	<u>NONE</u>	<u>WITHIN AREA OF IMPACT</u>		

E. GRAPHIC DESCRIPTION OF LEAK POINT (while detail report of the leak point should be contained in the leak report, overview sketch of the site should be added as an appendix 1)

A SECTION OF 24" BOMU-BONNY PIPELINE AT KPOR SHOWING HACK SAW CUT AT 2 O' CLOCK POSITION



F: TABLE SHOWING SOME OF COORDINATES TAKEN DURING JIV FOR AREA CALCULATION

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 10C7829 JIV report S/N: 0340

19. Impacted area boundary Coordinates (If more, Print and attach as an appendix)

MUNNA ND-BELT

S/N	Northing METERS	Easting METERS
	72555.57	534926.97
	72555.55	534942.38
	72521.80	534920.75
	72509.50	534926.89
	72506.41	534936.13
	72503.33	534942.29
	72484.91	534936.10
	72472.63	534929.91
	72535.19	534923.15
	72534.04	534942.35
	72520.39	534980.21
	72469.82	534978.28
	72428.13	534985.61
	72362.90	534979.82
	72332.59	534979.44
	72328.35	534927.32
	72422.81	534917.67

**G. INCIDENT INFORMATION:**

20. Impacted Area Details

- Total calculated area of impact 1.15Hr
- Impact within SPDC R.O.W YES
- Impact outside SPDC R.O.W \_\_\_\_\_

21. Volume of oil recovered before completion of JIV (V<sub>rec</sub>):

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1067829 JIV report S/N: 0340

Recovered oil $V_{recf}$ :	<u>NIL</u>	Barrels
----------------------------	------------	---------

22. Computation of estimated residual volume on site

a. Computation of estimated volume of pool of free phase oil (on land or confined water body).

- i. Area ( $m^2$ ) occupied by pool of free phase oil 11,200
- ii. Average Depth (m) of pool of free phase oil 0.004
- iii. Emulsification factor: NIL

iv.

Estimated Volume of pool of free phase oil.	<u>281.79</u>	barrels
$V_{pool}$ :		

b. Computation of estimated volume of infiltrated oil in the soil ( $V_{int}$ ).

1. Estimated Volume of infiltrated oil at spill point ( $V_{inf a}$ )

- i. Area\* ( $m^2$ ) of soil covered by the oil: 20  $m^2$
- ii. Average Depth (m) above leaking facility i.e. pipeline/flowline: 1m
- iii. Soil type: SILT iv.  $P_e$  (effective porosity of the soil): 21%
- v. Cause of spill: THIRD PARTY INTERFERENCE Oil type: BONNY MEDIUM
- vii. Oil Residence time on site, day: 2 DAYS
- viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline: 0.0018m
- ix. Estimated depth of infiltration around spill point: 1.0018m

Estimated Volume of infiltrated oil at spill point. $V_{inf a}$ :	<u>26.47</u>	barrels
---	--------------	---------

2. Estimated Volume of infiltrated oil at second spill point [if applicable] ( $V_{inf b}$ )

- i. Area\* ( $m^2$ ) of soil covered by the oil: NOT
- ii. Average Depth (m) above leaking facility i.e. pipeline/flowline:
- iii. Soil type:                      iv.  $P_e$  (effective porosity of the soil):
- v. Cause of spill:                      vi. Oil type:
- vii. Oil Residence time on site, day: APPLICABLE
- viii. Average depth of infiltration below leaking facility i.e. pipeline/flowline:
- ix. Estimated depth of infiltration around spill point:

Estimated Volume of infiltrated oil at spill point. $V_{inf b}$ :	<u>NIL</u>	barrels
---	------------	---------

3. E

Estimated Volume of infiltrated oil outside immediate spill point(s) region ( $V_{inf c}$ )

- i. Area ( $m^2$ ) of soil covered by the oil: 300
- ii. Area ( $m^2$ ) of the pool of free phase oil in touch with soil: 11200
- iii. Average Depth (m) below ground surface of infiltration of oil: 0.002m
- iv. Soil type: SILT
- v.  $P_e$  (effective porosity of the soil): 21%

vi.

Estimated Volume of infiltrated oil. At $V_{inf c}$ :	<u>30.39</u>	barrels
---	--------------	---------

23. Computation of estimated volume of oil on open water based on standard coloration.

Total area of oil on open water: NIL

**THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.**

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1067829 JIV report S/N: 0340

ii. Table of average depth of oil on water based on coloration (\*\*Spill Factors from USCG FOG (2000 Edition))

	Thickness (mm)	Percentage coverage	Volume (m3)
Barely Visible	0.00004	<b>NOT</b>	
Silvery	0.00008		
Slight Color	0.00015		
Bright Color	0.0003		
Dull	0.001	<b>APPLICABLE</b>	
Dark	0.002		
Black oil	0.1		
Emulsion (30% Oil)	1		

iii.	Percent Total	100%
	Estimated Volume of oil on open water. $V_{wat}$ :	<u>Nil</u> Barrels

24. Calculation of evaporated volume:

i. Estimated Volume available for evaporation within surface area: 338.64

ii. E-Factor: 15%

iii.	Estimated Volume of evaporated oil. $V_{evap}$ :	<u>59.76</u> Barrels
------	--	----------------------

Evaporation Factors (E-Factor) for SPDC Crude oil			
Oil Type	Days on site	Bonny Light	Bonny Medium
Oil Residence time	< 1 day	10%	5%
	1-7 days	25%	15% ✓
	> 7 days	40%	25%

25. Net Estimated Spilled Volume  $V_{net}(bbls) = V_{evap}(bbls) + V_{wat}(bbls) + V_{inf}(bbls) + V_{pool}(bbls) + V_{res}(bbls) =$   
 $59.76 + Nil + 56.85 + 281.79 + Nil = 398.4 \approx 399 \text{ BARRELS}$

Estimated Reported Volume  $V_{rep}(bbls) = 399 \text{ BARRELS}$

Calculation of the respective estimated volume is to be done on site as far as practicable using the new spill volume estimation software on site; Conversion of  $m^3$  to barrels is  $Volume (m^3) \times 6.29$ ; \*\*Round up estimated volume to next whole number using the following rules:

- Any spill volume in excess of 1 bbl is rounded up to the next whole number.
- Any spill volume in less than 1 bbl is rounded up to the next 0.1 bbl.

Examples: Calculated volume = 15.3 bbl ----- Reported volume = 16 bbl  
 Calculated volume = 0.35 bbl ----- Reported volume = 0.4 bbl  
 Calculated volume = 0.01 bbl ----- Reported volume = 0.1 bbl.

Wherever this estimation tool is not applicable please refer to paragraph 6c (Deviations) of the JIV procedure to use appropriate steps for column estimation; record the calculation in a plain sheet of paper and attach to the JIV report.

**26. GENERAL STATUS OF THE SITE**

A. Joint investigation of the incident site found that there is no residual impact after the initial response and therefore recommend that the site be closed out

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1067829 JIV report S/N: 0340

B. Investigation of the incident site showed that there is residual impact on site requiring further works

27. REPRESENTATIVES

This report was filled, agreed and signed on the 10 / 11 / 20 13 by joint investigation representatives from

- Host Community:
- Department of Petroleum Resources [DPR]:
- National Oil Spill Detection and Response Agency [NOSDRA]:
- State Ministry of Environment [SME]:
- Nigeria Police Force [NPF]:
- Shell Petroleum Development Company [SPDC]:
- Signatories agree with reported findings:
- Separate DPR form has been filled out with same findings

*Tick as applicable*

28. Appendix 1: Overview sketch of the site

Location :

THE SHELL PETROLEUM DEVELOPMENT COMPANY OF NIGERIA LIMITED.

JOINT INVESTIGATION REPORT FOR INCIDENT NO: 1067829 JIV report S/N: 0340

24" BOMU-BONNY PIPELINE AT KPOR/K-DERE

