



Overview: Part of spill/fire impact on 24" Bomu – Nkpoku Pipeline at Kpите. Picture was taken during Joint Investigation of 7th November 2013.



Close-up: Hacksaw cut on 24" Bomu - Nkpoku Pipeline at Kpите. Picture was taken during Joint Investigation of 7th November 2013.