



Overview: Part of spill impact on 24" Nkpoku - Bomu Trans Niger Pipeline right of way at Eteo. Picture was taken during Joint Investigation of 20th November 2013.



Close-up: Illegal fitting on 24" Nkpoku - Bomu Trans Niger Pipeline at Eteo. Picture was taken during Joint Investigation of 20th November 2013.