



Overview: Part of spill impact on 28" Bomu-Bonny Trans Niger Pipeline right of way at B-dere. Picture was taken during Joint Investigation of 13th November 2013.



Close-up: Hacksaw cut on ImoRiver Well21L Flowline at Igiriukwu/Isietitioha. Picture was taken during Joint Investigation of 13th November 2013.