



Overview: Part of spill impact on 24" Bomu-Bonny Pipeline right of way at Kpor. Picture was taken during Joint Investigation of 10th November 2013.



Close-up: Hacksaw cut on 24" Bomu-Bonny Pipeline at Kpor. Picture was taken during Joint Investigation of 10<sup>th</sup> November 2013.



Close-up: Hacksaw cut on 24" Bomu-Bonny Pipeline at Kpor. Picture was taken during Joint Investigation of 10<sup>th</sup> November 2013.