




Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline right of way at Ikarama. Picture was taken during Joint Investigation of 6th November 2013.



Close-up: Hacksaw cut on 14" Okordia-Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 6th November 2013.