



Overview: Part of spill impact on Elenwo Well9LS Wellhead at Elenwo. Picture was taken during Joint Investigation of 12th December 2013.



Close-up: Failed valve on Elenwo Well9LS Wellhead at Elenwo. Picture was taken during Joint Investigation of 12th December 2013.