



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 29th November 2013.



Close-up: Nuts removed from clamp on 28" Nkpoku-Bomu Pipeline at Gio. Picture was taken during Joint Investigation of 29th November 2013.