



Overview: Part of spill impact on 20" Opukushi-Brass Creek Trunkline right of way at Tamogbene. Picture was taken during Joint Investigation of 30th November 2013.



Close-up: Illegal fitting on 20" Opukushi-Brass Creek Trunkline at Tamogbene. Picture was taken during Joint Investigation of 30th November 2013.