




Overview: Part of spill impact on 12" Estuary LP Delivery line Right of Way at Youbebe. Picture was taken during Joint Investigation of 8th November 2014.



Close-up: Bubbling from corrosion on 12" Estuary LP Delivery line at Youbebe. Picture was taken during Joint Investigation of 8th November 2014.