



Overview: Spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Norkpo. Picture was taken during Joint Investigation of 6th November 2014.



Close-up: Drilled holes on 28" Nkpoku-Bomu Pipeline at Norkpo. Picture was taken during Joint Investigation of 6th November 2014.