



Close-up: Fire on Akaso Well3 Wellhead at Ilomaturu. Picture was taken during Overfly of 3<sup>rd</sup> November 2014.



Overview: Part of spill impact on Akaso Well3 Wellhead Right of Way at Ilomaturu. Picture was taken during Joint Investigation of 7<sup>th</sup> November 2014.



Close-up: Fire damage on Akaso Well3 Wellhead at Ilomaturu. Picture was taken during Joint Investigation of 7<sup>th</sup> November 2014.