



Overview: Part of spill impact on 8" Nkpoku-Bomu Pipeline Right of Way at Umuechem. Picture was taken during Joint Investigation of 13th November 2014.



Close-up: Illegal fitting on 8" Nkpoku-Bomu Pipeline at Umuechem. Picture was taken during Joint Investigation of 13th November 2014.