



Overview: Site of spill on 4" Ahia Well3S Flowline Right of Way at Egbeda. Picture was taken during Joint Investigation of 18th November 2014.



Close-up: Cut section on 4" Ahia Well3S Flowline at Egbeda. Picture was taken during Joint Investigation of 18th November 2014.