



Overview: Part of spill impact on 12" Imo River2 – Ogale Pipeline Right of Way at Owaza. Picture was taken during Joint Investigation of 14th November 2014.



Close-up: Illegal fitting on 12" Imo River2 – Ogale Pipeline at Owaza. Picture was taken during Joint Investigation of 14th November 2014.