



Overview: Part of spill impact on Tunu Wellhead 4LS Right of Way at Bilabiri. Picture was taken during Joint Investigation of 29<sup>th</sup> November 2014.



Close-up: Location of stolen Control Unit (Well-4L) on Tunu Wellhead 4LS at Bilabiri. Picture was taken during Joint Investigation of 29<sup>th</sup> November 2014.



Close-up: Location of stolen Control Unit (Well-4S) on Tunu Wellhead 4LS at Bilabiri. Picture was taken during Joint Investigation of 29<sup>th</sup> November 2014.