



Overview: Part of spill impact on 24" Bomu-Bonny Pipeline Right of Way at Okolo Launch. Picture was taken during Joint Investigation of 27th November 2014.



Close-up: Position of failed illegal fitting on 24" Bomu-Bonny Pipeline at Okolo Launch. Picture was taken during Joint Investigation of 25th November 2014.