



Overview: Part of spill impact on 4" Etelebou Well 11T Flowline Right of Way at Ogboloma. Picture was taken during Joint Investigation of 2nd December 2014.



Close-up: Hacksaw cut on 4" Etelebou Well 11T Flowline at Ogboloma. Picture was taken during Joint Investigation of 2nd December 2014.