



Overview: Spill point on Alakiri Well19T Wellhead Right of Way at Ofiomina-Ama. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2014.



Close-up: Exposed internal thread tape on Alakiri Well19T Wellhead at Ofiomina-Ama. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2014.



Close-up: Position of missing bean cap on Alakiri Well19T Wellhead at Ofiomina-Ama. Picture was taken during Joint Investigation of 24<sup>th</sup> November 2014.