



Overview: Part of spill impact on 6" Odeama-Tora Pipeline Right of Way at Bassambiri. Picture was taken during Joint Investigation of 19th November 2014.



Close-up: Illegal fitting on 6" Odeama-Tora Pipeline at Bassambiri. Picture was taken during Joint Investigation of 19th November 2014.