



Overview: Part of spill impact on 14" Okordia-Rumuekpe Pipeline Right of Way at Ikarama. Picture was taken during Joint Investigation of 21<sup>st</sup> November 2014.



Close-up: Spill due to corrosion on 14" Okordia-Rumuekpe Pipeline at Ikarama. Picture was taken during Joint Investigation of 22<sup>nd</sup> November 2014.