



Overview: Part of spill impact on 28" Nkpoku-Bomu Pipeline Right of Way at Elenwo. Picture was taken during Joint Investigation of 25th November 2014.



Close-up: Illegal fittings on 28" Nkpoku-Bomu Pipeline at Elenwo. Picture was taken during Joint Investigation of 25th November 2014.