



Overview: Part of spill impact on Ahia Well3SL Flowline Right of Way at Egbeda. Picture was taken during Joint Investigation of 14th November 2014.



Close-up: Hacksaw cut on Ahia Well3SL Flowline at Egbeda. Picture was taken during Joint Investigation of 14th November 2014.