



Overview: Part of spill and fire impact on 28" Bomu-Bonny Pipeline Right of Way at Mogho. Picture was taken during Joint Investigation of 28th November 2014.



Close-up: Illegal fitting on 28" Bomu-Bonny Pipeline at Mogho. Picture was taken during Joint Investigation of 28th November 2014.