



Overview: Part of spill impact on 24" Tora - Segoo Pipeline Right of Way at Segoo. Picture was taken during Overfly of 21<sup>st</sup> November 2014.



Close-up: Spill due to corrosion on 24" Tora - Segoo Pipeline at Segoo. Picture was taken during Repair Operation of 7<sup>th</sup> December 2014.