



Overview: Part of spill impact on 6" Yokri Manifold7 Test Flowline Right of Way at Yokri. Picture was taken during Joint Investigation of 12th of December 2014.



Close-up: Spill point on 6" Yokri Manifold7 Test Flowline at Yokri. Picture was taken during Joint Investigation of 12th of December 2014.