



Overview: Location of spill on Tunu Kanbo Well4L Wellhead Right of Way at Agbidiana .
Picture was taken during Joint Investigation of 21st November 2015.



Close-up: Original position of Cameron Control Unit on Tunu Kanbo Well4L Wellhead at Agbidiana . Picture was taken during Joint Investigation of 21st November 2015.