



Overview: Part of spill impact on 28" Bomu-Bonny Pipeline at Otokolomabie/Oloma. Picture was taken during Joint Investigation of 30th November 2015.



Close-up: Position of illegal fitting after removal on 28" Bomu-Bonny Pipeline at Otokolomabie/Oloma. Picture was taken during Joint Investigation of 30th November 2015.