


Overview: Part of spill impact on 16" Nun River-KoloCreek Pipeline Right of Way at Agbura_Otuokpoti. Picture was taken during Joint Investigation of 1st January 2018.



Close-up: Position of completely broken pipeline on 16" Nun River-KoloCreek Pipeline at Agbura_Otuokpoti. Picture was taken during Joint Investigation of 1st January 2018.