




Overview: Part of spill impact on 20" Kolocreek-Rumuekpe Pipeline Right of Way at Odau. Picture was taken during Joint Investigation of 2<sup>nd</sup> December 2017.



Close-up: Illegal fitting on 20" Kolocreek-Rumuekpe Pipeline at Odau. Picture was taken during Joint Investigation of 30<sup>th</sup> November 2017.