


**Overview:** Part of spill impact on 28" Nkpoku - Bomu Pipeline Right of Way at Rumuowha-Eneka. Picture was taken during Joint Investigation of 30<sup>th</sup> November 2018.



**Close-up:** Leaking Illegal fitting on 28" Nkpoku - Bomu Pipeline at Rumuowha-Eneka. Picture was taken during Joint Investigation of 30<sup>th</sup> November 2018.