



Overview: Part of spill impact on 16" Egbema - Assa Pipeline Right of Way at Umudike. Picture was taken during Joint Investigation of 20th November 2018.



Close-up: Illegal fittings on 16" Egbema - Assa Pipeline at Umudike. Picture was taken during Joint Investigation of 20th November 2018.