




Overview: Part of spill impact on 24inch Ogale Bomu Pipeline at Agbeta.
 Picture was taken during Joint Investigation on 22nd November 2020



Close-up: Vandalized clamp bolts (11 pieces removed) on 24inch Ogale Bomu Pipeline at Agbeta.
 Picture was taken during Joint Investigation on 22nd November 2020