



Overview: Part of spill impact on 12inch Imoriver 1 - Ogale Pipeline at Komkom.
 Picture was taken during Joint Investigation on 30th November 2020.



Close-up: 1.5inch pipe fitted with 2nos of 1.5inch valves installed at 12 o'clock position on 12''
 Imoriver 1 - Ogale Pipeline at Komkom.
 Picture was taken during Joint Investigation on 30th November 2020.