



Overview: Part of spill impact on 20inch Kolocreek – Rumuekpe Trunkline at Owerewere. Picture was taken during Joint Investigation on 23rd November 2020.



Close-up: 2inch valve installed at 12 o'clock position on 20inch Kolocreek – Rumuekpe Trunkline at Owerewere. Picture was taken during Joint Investigation on 23rd November 2020.