



Overview: Part of spill impact on 6'' Seibuo Well 3 & 4 Bulkline at Agbidiana. Picture was taken during Joint Investigation on 11th December 2020.



Close-up: Hack Saw Cut on 6'' Seibuo Well 3 & 4 Bulkline at Agbidiana. Picture was taken during Joint Investigation on 11th December 2020.