


**Overview:** Part of spill impact on 12inch Oguta Egbema Pipeline at Ukwugba. Picture was taken during Joint Investigation on 25th November 2020.



**Close-up:** 2inch valve illegal connection installed at 12 o'clock position on 12inch Oguta - Egbema Pipeline at Ukwugba. Picture was taken during Joint Investigation on 25th November 2020.